

Assembly Instructions



CODE 830

ISO-SHIPPER SYSTEM XP-20


Winter Configuration

+2.0°C to +8.0°C for 48 Hours

Air Sea Containers Ltd, 521 Cavendish Street, Birkenhead, CH41 8FZ

Tel:+44(0) 151 653 1500 Fax: +44(0) 151 653 1515

Website: www.air-sea.co.uk Email: sales@air-sea.co.uk



Bill of Materials

- 1 x TC-20 EPS SHIPPER
- 1 x Printed Outer Carton
- 7 x CP2020 CoolPacks @ +5°C
- 1 x CP2020 Cool Pack @ -18°C
- 2 x EPS Spacers (180 x 180 x 20mm)
- Inner Carton (Not Supplied)

Pre - Assembly Instructions

- 1 x Cool Pack illustrated YELLOW should be stored @ -18° C in a cold store for a minimum of 48 hours prior to use.
- 7 x Cool Pack illustrated BLUE should be stored @ +5° C in a cold store for a minimum of 48 hours prior to use.

Assembly Instructions

- Once Cool Packs have been stored as indicated in the pre-assembly instructions they can be placed into the shipper, immediately.
- Place Cool Pack around the product as indicated on the diagram.
- Fit EPS shipper lid on top and secure outer carton flaps once the Cool Packs and product are assembled.